Gerald Nielsen

IN THE UNITED STATES DISTRICT COURT FOR THE DISTRICT OF SOUTH CAROLINA CHARLESTON DIVISION IN ADMIRALTY

- - -

TIFFANY N. PROVENCE, as the :
Personal Representative of the :
Estate of Juan Antonia :
Villalobos Hernandez, :

:

Plaintiff,

: Case No.

vs. : 2:21-cv-965-RMG

:

UNITED STATES OF AMERICA,
CROWLEY MARITIME CORPORATION,
CROWLEY GOVERNMENT SERVICES,
INC., DETYENS SHIPYARDS, INC.,
and HIGHTRAK STAFFING, INC,
d/b/a Hitrak Staffing, Inc.,

:

Defendants.

:

DEPOSITION OF GERALD NIELSEN

DATE TAKEN: Monday, April 11, 2022

TIME BEGAN: 10:00 a.m.

TIME ENDED: 5:20 p.m.

LOCATION: REMOTE PARTICIPATION DEPOSITION

(All parties participated via videoconference)

REPORTED BY: Mary Posey, Court Reporter

EveryWord, Inc. P.O. Box 1459

Columbia, South Carolina 29202

803-212-0012



Gerald Nielsen

| 1 | had a secondary means of retention or had been |
|----|---|
| 2 | removed, and if left as is, there were multiple |
| 3 | opportunities for the hazard to have been identified |
| 4 | and rectified. |
| 5 | Q Okay. And the hazard in question was a |
| 6 | stray electrical current. Was the mechanism a |
| 7 | failure? |
| 8 | A The hazard was the stored energy, the davit |
| 9 | being secured in an area where gravity could work on |
| LO | it if you lost your retention, so the hazard was the |
| L1 | stored energy. The risk was that something could |
| L2 | happen to release that stored energy. That risk |
| L3 | manifested itself in the way of a stray current. |
| L4 | Q Okay. And with respect to that, the risk |
| L5 | of the stray current, we don't know where it came |
| L6 | from but most probably it was from ungrounded welding |
| L7 | at some point prior to this incident. |
| L8 | A That's my understanding, yes. |
| L9 | Q Okay. And you also agree that these davit |
| 20 | arms on this ship, all 12 of them, had been |
| 21 | successfully restrained for five months. |
| 22 | A From sometime in November to sometime in |
| 23 | April. So yes, approximately five months. Correct. |
| 24 | Q Okay. And that this method of constraint |
| 25 | would have been visible to the Detyens safety |

Page: 185

